

FIG. 1 PRIOR ART

FIG. 2 PRIOR ART




FIG. 3
PRIOR ART

FIG. 4




FIG. 5




FIG. 6

$T_x^1 \int 1$	0	0	1	0	0	1	•••	0	0	1]
$T_x^2 = 0$	1	0	0	1	0	0	• • •	1	0	0
$ \begin{array}{c c} T_x^1 & 1 \\ T_x^2 & 0 \\ T_x^3 & 0 \end{array} $	Q	1	0	0	1	0	•••	0	1	0
$R_x[H_1]$	H_{2}^{2}	H_3^3	H_{4}^{1}	H_5^2	H_{6}^{3}	$H^{\frac{1}{7}}$	•••	$H_{50}^{\ 2}$	H_{51}^{3}	H_{52}^{1}

FIG. 7




FIG. 8
PRIOR ART

900

Tx1						(di	1	\L\1	77	71	<u>_†2</u>		SIGNAL				
Tx2						G	1	LT/I	\prod		LT2	T	\prod	S	Gή	ΑЦ	
İ		į		-				11							\ '	\ \	
1		!	,	!		$ \cdot $		1 1					\		1	1	
1		į					<u> </u>	\perp	\sqcup !	\perp		\Box				11	
TxNt						φı	1	LT1		1	L\2	1 1		\$	GN	IA/L \	

FIG. 9

$ \begin{array}{ccc} T_x^1 & 1 \\ T_x^2 & 0 \end{array} $	0 1	1 0	0 1	1 0	0 1	1 0	•••	0 1	1 0	$\begin{bmatrix} 0 \\ 1 \end{bmatrix}$
$\int H_{1}^{1}$	0	0	H_{4}^{2}	0	0	$H^{\frac{1}{7}}$	• • •	0	0	H_{52}^{2}

$$\begin{bmatrix}
H_{1}^{1} & 0 & 0 & H_{4}^{2} & 0 & 0 & H_{7}^{1} & \cdots & 0 & 0 & H_{52}^{2} \\
0 & H_{2}^{2} & 0 & 0 & H_{5}^{1} & 0 & 0 & \cdots & H_{50}^{2} & 0 & 0 \\
0 & 0 & H_{3}^{1} & 0 & 0 & H_{6}^{2} & 0 & \cdots & 0 & H_{51}^{1} & 0
\end{bmatrix}$$

FIG. 10

1100

Tx1				(d)		7	L 1 (1	7	V	/LT/2		\Box	S	GŅΑ	44									1
Tx2				\GI\	\prod		ĻT∤	\mathcal{I}	\prod	ĻΤģ	II	\prod	/si	GN X	AL\								~~~	i
Tx3				ĠI	V	\mathcal{I}	<u>Γ</u> /11	\sum_{j}		<u>r/t</u> 2/	\perp		ŞI	ġΝ/	<u>ل</u> /									
Tx4										~·· ········					\ m + 15 + 1	7	Ġί		\L	1/3 /		7	<u> ۲14</u>	$\Delta 1$
Tx5																Ì	Ġ1/	Γ	1	<u> [3/</u>	7	7	<u>L(T4</u>	L_{\perp}

FIG. 11

WO 2005/006588 PCT/US2004/021026




FIG. 12